

INTERNAL CARGO DAMAGE REPORT

AWB NO: 058-021 5486

CARGO CLAIMS

Loss prevention program

General Information

Reported By praneeth	Incident Date 2019-08-14	Incident Time 12:04 AM	Reporting station AMS
--------------------------------	------------------------------------	----------------------------------	---------------------------------

Job Function
chander

Airway Bill and Flight Information

Airline Indian Airlines	Movement Inbound	Transport Type -----	Number 058
Master Airway Bill 058-021 5486	Date 2019-08-07	Airport Of Origin Guildwood Rail Station-XLQ	Airport Of Destination Sudbury Municipal Airport-YSB

Shipment Information

Content Nature 1	MAWB Total Pieces 1	Actual Received Pieces 1	Consignee Name praneeth
Shipper Name praneeth	MAWB Total Kilograms 1	Actual Received Kilograms 1	Issuing Agent praneeth

Damage Information

Method Of Packing ULD	Identification No hi	Safety Threat no	Affected House AWB'S dcas
Damage to Packing torn	Content Affected no	Items Missing No	Condition Of Content Soiled
Suspected of Pilferage no	Affected Pcs -----	Items Missing Pcs -----	Affected Weight -----
Items Missing Kg -----	Recuperation Required No	Recuperation Status No,lack of time	Classification Type Minor-Small tears,dents or scratches to the outer packaging only.

Investigation and Responsibility

Damage Discovered In AC compartment	Discovers By Caused -----	Internal Name praneeth	Internal Group chander
Internal Code 9854	Internal Responsibility external	Internal Area -----	Area Supervisor -----
Exact Location -----	Locaton Id -----	Cause Of Event -----	

Upload Pictures and Documents

Damage Images

Damage Report