## INTERNAL CARGO DAMAGE REPORT

AWB NO: 002-56356434



General Information			
<b>Reported By</b> castus	Incident Date 2019-09-09	Incident Time 4:54 PM	Reporting station YSM
Job Function sasas			
Airway Bill and Flight Info	ormation		
<b>Airline</b> Cargoitalia	Movement	<b>Transport Type</b> flight	Number 4343
<b>Master Airway Bill</b> 002-56356434	<b>Date</b> 2019-09-09	Airport Of Origin Drangedal Rail Station-ZVD	Airport Of Destination Winnipeg International Airport-YWG
Shipment Information			
<b>Content Nature</b> sdfsdfsf	MAWB Total Pieces	Actual Received Pieces	Consignee Name
Shipper Name	Issuing Agent		
Damage Information		$\sim 10^{-1}$	
Method Of Packing	Identification No	<b>Safety Threat</b> No	Affected House AWB'S
Damage to Packing Broken,Crushed	Content Affected No	<b>Items Missing</b> No	Condition Of Content
Suspected of Pilferage	Affected Pcs	Items Missing Pcs	Affected Weight
Recuperation Requried Yes	Recuperation Status	<b>Classification Type</b> Pilferage - Cargo suspected o Pilferage Inspection is Required	f
Investigation and Responsibility			
Damage Discovered During loading	Discoveres By Caused discoveredby	<b>Internal Name</b> ddfgdfg	Internal Group 
Internal Code	Internal Responsibility external	Internal Area	Area Supervisor
Exact Location	Locaton Id	Cause Of Event	

AWB NO: 002-56356434



Upload Pictures and Documents

Damage Images

-----