## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-12347757



**General Information** 

Reported By Incident Date Incident Time Reporting station

castus 2019-09-11 20:20 YSM

**Job Function** 

bigbee

**Airway Bill and Flight Information** 

AirlineMovementTransport TypeNumberYerevan Avia-------flight2222

Master Airway BillDateAirport Of OriginAirport Of Destination009-123477572019-09-11Amsterdam Airport Schiphol-Brussels National Airport-BRU

AMS

**Shipment Information** 

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

srdfqhbj ------

Shipper Name Issuing Agent

-----

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

----- No -----

Damage to Packing Content Affected Items Missing Condition Of Content

Shock watch, No ------

Suspected of Pilferage Affected Pcs Affected Weight Items Missing Pcs

------

Recovery Requried Recovery Status Classification Type

------ Minor - Small tears, dents or scratches to the outer

packaging only

Investigation and Responsibility

Damage DiscoveredWas the damageNameGroup------discoveredbysdfg-------

Responsibility Process Area Area Supervisor Exact Location

external ------

Locaton Id Cause Of Event

no-reply@cclp.aero 1

## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-12347757



**Upload Pictures and Documents** 

Damage Images

-----

no-reply@cclp.aero 2