## INTERNAL CARGO DAMAGE REPORT

AWB NO: 009-34345688



Group

**General Information** 

Reported By **Incident Date Incident Time Reporting station** 

2019-09-10 castusinfosolution 16:33 **AMS** 

**Job Function** 

**Airway Bill and Flight Information** 

Airline **Transport Type** Number Movement Yerevan Avia 4444 flight -----

**Master Airway Bill Airport Of Origin Airport Of Destination** Date 009-34345688 2019-09-10 Amsterdam Airport Schiphol- Brussels National Airport-BRU

**AMS** 

**Shipment Information** 

**Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name** 

srdfghbj

**Shipper Name Issuing Agent** 

**Damage Information** 

**Damage Discovered** 

**Method Of Packing Identification No Safety Threat** Affected House AWB'S

No

**Damage to Packing Content Affected Items Missing Condition Of Content** 

Seal open,

**Suspected of Pilferage Affected Pcs Affected Weight Items Missing Pcs** 

**Recovery Requried Recovery Status Classification Type** 

Minor - Small tears, dents or scratches to the outer

packaging only

**Investigation and Responsibility** 

Was the damage Discovered Name sdfg

discoveredby

Responsibility **Process Area Exact Location Area Supervisor** 

external

Locaton Id **Cause Of Event** 

1 no-reply@cclp.aero

## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 009-34345688



**Upload Pictures and Documents** 

Damage Images

\_\_\_\_\_

no-reply@cclp.aero 2