

INTERNAL CARGO DAMAGE REPORT

AWB NO: 998-257k575

General Information

Reported By magnitia	Incident Date 2019-09-10	Incident Time 17:04	Reporting station AMS
--------------------------------	------------------------------------	-------------------------------	---------------------------------

Job Function

Airway Bill and Flight Information

Airline Yerevan Avia	Movement -----	Transport Type flight	Number 545
Master Airway Bill 998-257k575	Date 2019-09-10	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature ADad	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
-------------------------------	-----------------------------------	--	--------------------------------

Shipper Name -----	Issuing Agent -----
------------------------------	-------------------------------

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat No	Affected House AWB'S -----
-----------------------------------	-----------------------------------	----------------------------	--------------------------------------

Damage to Packing Dented,Broken,	Content Affected No	Items Missing No	Condition Of Content -----
--	-------------------------------	----------------------------	--------------------------------------

Suspected of Pilferage -----	Affected Pcs -----	Affected Weight -----	Items Missing Pcs -----
--	------------------------------	---------------------------------	-----------------------------------

Recovery Required No	Recovery Status -----	Classification Type Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)
--------------------------------	---------------------------------	---

Investigation and Responsibility

Damage Discovered -----	Was the damage Discovered By discoveredby	Name sdas	Group -----
-----------------------------------	---	---------------------	-----------------------

Responsibility external	Process Area -----	Area Supervisor -----	Exact Location -----
-----------------------------------	------------------------------	---------------------------------	--------------------------------

Locaton Id -----	Cause Of Event -----
----------------------------	--------------------------------

Upload Pictures and Documents

Damage Images

Damage Report