

**INTERNAL CARGO DAMAGE REPORT**

AWB NO: 998-32g32131

**General Information**

<b>Reported By</b> castus	<b>Incident Date</b> 2019-09-10	<b>Incident Time</b> 19:30	<b>Reporting station</b> ZHO
------------------------------	------------------------------------	-------------------------------	---------------------------------

**Job Function**  
supervisor

**Airway Bill and Flight Information**

<b>Airline</b> Yerevan Avia	<b>Movement</b> -----	<b>Transport Type</b> flight	<b>Number</b> 3211
<b>Master Airway Bill</b> 998-32g32131	<b>Date</b> 2019-09-10	<b>Airport Of Origin</b> Amsterdam Airport Schiphol-AMS	<b>Airport Of Destination</b> Brussels National Airport-BRU

**Shipment Information**

<b>Content Nature</b> ZXCX	<b>MAWB Total Pieces</b> -----	<b>Actual Received Pieces</b> -----	<b>Consignee Name</b> -----
<b>Shipper Name</b> -----	<b>Issuing Agent</b> -----		

**Damage Information**

<b>Method Of Packing</b> -----	<b>Identification No</b> -----	<b>Safety Threat</b> No	<b>Affected House AWB'S</b> -----
<b>Damage to Packing</b> Crushed,Tape torn,	<b>Content Affected</b> No	<b>Items Missing</b> No	<b>Condition Of Content</b> -----
<b>Suspected of Pilferage</b> -----	<b>Affected Pcs</b> -----	<b>Affected Weight</b> -----	<b>Items Missing Pcs</b> -----
<b>Recovery Required</b> No	<b>Recovery Status</b> -----	<b>Classification Type</b> Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)	

**Investigation and Responsibility**

<b>Damage Discovered</b> -----	<b>Was the damage discovered by</b> -----	<b>Name</b> xzcxcvcb	<b>Group</b> -----
<b>Responsibility</b> external	<b>Process Area</b> -----	<b>Area Supervisor</b> -----	<b>Exact Location</b> -----
<b>Locaton Id</b> -----	<b>Cause Of Event</b> -----		

Upload Pictures and Documents

**Damage Images**

-----

Damage Report