## INTERNAL CARGO DAMAGE REPORT

AWB NO: 998-52488888



**General Information** 

Reported By **Incident Date Incident Time Reporting station** 

2019-09-10 magnitia 17:27 **AMS** 

**Job Function** 

**Airway Bill and Flight Information** 

Airline **Transport Type** Number Movement Yerevan Avia flight 2111 -----

**Airport Of Destination Master Airway Bill Airport Of Origin** Date

Amsterdam Airport Schiphol- Brussels National Airport-BRU 998-52488888 2019-09-10 **AMS** 

**Shipment Information** 

**Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name** 

Fghj

**Shipper Name Issuing Agent** 

**Damage Information** 

**Method Of Packing Identification No Safety Threat** Affected House AWB'S

No

**Content Affected Damage to Packing Items Missing Condition Of Content** 

Broken, Crushed, No

**Suspected of Pilferage Affected Pcs Affected Weight Items Missing Pcs** 

**Recovery Requried Recovery Status Classification Type** 

Minor - Small tears, dents or No scratches to the outer

packaging only

**Investigation and Responsibility** 

**Damage Discovered** Was the damage Discovered Name Group

dSD discoveredby

Responsibility **Process Area Area Supervisor Exact Location** 

external

Locaton Id **Cause Of Event** 

1 no-reply@cclp.aero

## **INTERNAL CARGO DAMAGE REPORT**

AWB NO: 998-52488888



**Upload Pictures and Documents** 

Damage Images

-----

no-reply@cclp.aero 2