INTERNAL CARGO DAMAGE REPORT

AWB NO: 998-68686989



General Information

Reported By Incident Date Incident Time Reporting station

cognizant 2019-09-09 4:33 PM BRU

Job Function

nxnd

Airway Bill and Flight Information

AirlineMovementTransport TypeNumberYerevan Avia-------flight9798

Master Airway BillDateAirport Of OriginAirport Of Destination998-686869892019-09-09Amsterdam Airport Schiphol-Brussels National Airport-BRU

AMS

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

dh ------

Shipper Name Issuing Agent

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

----- Yes ------

Damage to Packing Content Affected Items Missing Condition Of Content

Crushed, Tape torn No Yes ------

Suspected of Pilferage Affected Pcs Items Missing Pcs Affected Weight

No ------ 25 Affected weight

25

Recuperation RequriedRecuperation StatusClassification TypeYesLife Threat - Damage

involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or

spillage)

Investigation and Responsibility

Damage Discovered Discoveres By Caused Internal Name Internal Group

------ discoveredby hd ------

Internal Code Internal Responsibility Internal Area Area Supervisor

------ external -------

Exact Location Locaton Id Cause Of Event

no-reply@cclp.aero 1

INTERNAL CARGO DAMAGE REPORT

AWB NO: 998-68686989



Upload Pictures and Documents

Damage Images

no-reply@cclp.aero 2