

EXTERNAL CARGO DAMAGE REPORT

AWB NO: 070-94649494

General Information

Reported by -----	Reporting station AMS	Incident Date 2019-09-09	Incident Time 6:28 PM
-----------------------------	---------------------------------	------------------------------------	---------------------------------

Airway Bill and Flight Information

Airline Syrianair	Movement -----	Transport Type flight	Number 6466
Master Airway Bill 070-94649494	Date 2019-09-09	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature sh	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
Shipper Name -----	Issuing Agent -----		

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat Yes	Affected House AWB'S -----
Damage to Packing Dented,Broken	Content Affected No	Items Missing -----	Condition Of Content -----
Suspected of Pilferage Yes	Affected Pcs 25	Items Missing PCS -----	Affected Weight -----
Recuperation Required -----	Recuperation Status -----		

Risk classification

Affected Weight -----	Calculated risk [Based on Montreal Convention 19 SDR per Kilogram] -----
---------------------------------	--

Classification Type

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

Upload Pictures and Documents

Damage Images

Damage Report