

EXTERNAL CARGO DAMAGE REPORT

AWB NO: 618-986

General Information

Reported by -----	Reporting station AMS	Incident Date 2019-09-09	Incident Time 4:46 PM
-----------------------------	---------------------------------	------------------------------------	---------------------------------

Airway Bill and Flight Information

Airline Singapore Airlines Cargo	Movement -----	Transport Type flight	Number 66
Master Airway Bill 618-986	Date 2019-09-09	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature fj	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
Shipper Name -----	Issuing Agent -----		

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat Yes	Affected House AWB'S -----
Damage to Packing ,hx	Content Affected No	Items Missing Possibly	Condition Of Content -----
Suspected of Pilferage No	Affected Pcs -----	Items Missing PCS 25	Affected Weight -----
Recuperation Required -----	Recuperation Status -----		

Risk classification

Affected Weight -----	Calculated risk [Based on Montreal Convention 19 SDR per Kilogram] -----
---------------------------------	--

Classification Type

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

Upload Pictures and Documents

Damage Images

Damage Report