EXTERNAL CARGO DAMAGE REPORT

AWB NO: 998-11112222-11112222



General Information

Reported by **Reporting station Incident Date Incident Time** 2019-09-09

castus 13:45

Airway Bill and Flight Information

Airline Number **Transport Type** Movement 4444 Yerevan Avia flight

Master Airway Bill Airport Of Origin Airport Of Destination Date 998-11112222-11112222-1112019-09-09 Amsterdam Airport Schiphol- Brussels National Airport-BRU

12222

Shipment Information

Content Nature MAWB Total Pieces Actual Received Pieces Consignee Name

wdasfd

Shipper Name Issuing Agent

Damage Information

Method Of Packing Identification No Safety Threat Affected House AWB'S

Frame, No

Damage to Packing Content Affected Items Missing Condition Of Content

Tape torn, Tape loose, No

Suspected of Pilferage Affected Pcs **Items Missing PCS Affected Weight**

Recuperation Requried Recuperation Status

Risk classification

Affected Weight Calculated risk [Based on Montreal Convention 19 SDR per Kilogram]

Classification Type

Minor - Small tears, dents or scratches to the outer packaging only

1 no-reply@cclp.aero

AWB NO: 998-11112222-11112222



Upload Pictures and Documents

Damage Images





shutterstock.com • 192699476

no-reply@cclp.aero 2