

EXTERNAL CARGO DAMAGE REPORT

AWB NO: 998-545435

General Information

Reported by rapido	Reporting station AMS	Incident Date 2019-09-10	Incident Time 13:53
------------------------------	---------------------------------	------------------------------------	-------------------------------

Airway Bill and Flight Information

Airline Yerevan Avia	Movement -----	Transport Type flight	Number 4563
Master Airway Bill 998-545435	Date 2019-09-10	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature asdasd	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
Shipper Name -----	Issuing Agent -----		

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat Yes	Affected House AWB'S -----
Damage to Packing Crushed,Tape torn,	Content Affected No	Items Missing No	Condition Of Content -----
Suspected of Pilferage -----	Affected Pcs -----	Affected Weight -----	Items Missing PCS -----
Recovery Required -----	Recovery Status -----		

Risk classification

Affected Weight -----	Calculated risk [Based on Montreal Convention 19 SDR per Kilogram] -----
---------------------------------	--

Classification Type

Life Threat - Damage involving safety of life or property Inspection, Decontamination and verification is required.(e.g. chemical, biological, radioactive leakage or spillage)

Upload Pictures and Documents

Damage Images

Damage Report