

EXTERNAL CARGO DAMAGE REPORT

AWB NO: 998-55555555-55555555

General Information

Reported by castus	Reporting station AMS	Incident Date 2019-09-09	Incident Time 13:50
------------------------------	---------------------------------	------------------------------------	-------------------------------

Airway Bill and Flight Information

Airline Yerevan Avia	Movement -----	Transport Type truck	Number -----
Master Airway Bill 998-55555555-55555555	Date 2019-09-09	Airport Of Origin Amsterdam Airport Schiphol-AMS	Airport Of Destination Brussels National Airport-BRU

Shipment Information

Content Nature sdfgf	MAWB Total Pieces -----	Actual Received Pieces -----	Consignee Name -----
Shipper Name -----	Issuing Agent -----		

Damage Information

Method Of Packing -----	Identification No -----	Safety Threat No	Affected House AWB'S -----
Damage to Packing Seal open,	Content Affected No	Items Missing -----	Condition Of Content -----
Suspected of Pilferage -----	Affected Pcs -----	Items Missing PCS -----	Affected Weight -----
Recuperation Required -----	Recuperation Status -----		

Risk classification

Affected Weight -----	Calculated risk [Based on Montreal Convention 19 SDR per Kilogram] -----
	Classification Type Minor - Small tears, dents or scratches to the outer packaging only

Upload Pictures and Documents

Damage Images



shutterstock.com • 192699476

Damage Report